## SERVICE KIT 753-0560

CODE:

T-100

DATE:

AUGUST 19, 1992

SUBJECT:

**ENGINEERING REVISIONS** 

800-849 SERIES

TRACTOR

Due to engineering revisions made to the variable speed torque bracket assembly (Part No. 16990) and pulley bracket assembly (Part No. 17205), these parts cannot be replaced separately. When replacing either of these parts service kit 753-0560 must be installed. This kit contains both of the revised parts which must be replaced as a set.

## Service Kit 753-0560 consists of:

REF NO.	PART NO.	DESCRIPTION	QTY
1 2	17914 17908	Variable Speed Torque Brkt. Assy. Pulley Brkt. Plate Assy.	- 1 1

