SERVICE KIT 753-0589

CODE:

R-349

DATE:

January 24, 1994

SUBJECT:

Ignition Switch - 400 Series Rider

PROBLEM:

Defective Ignition Switch on the 400 Series Rider

SOLUTION:

Install Service Kit 753-0589

INSTALLATION INSTRUCTIONS

- 1. Disconnect the harness terminal block from the ignition switch on the unit.
- 2. Remove the igntion switch from the dash.
- 3. Install the new ignition switch provided in kit. Secure it to the dash.
- 4. Install the harness adapter provided in the kit to the wiring harness on the unit. Secure the other end of the adapter to the new ignition switch mounted in the dash.

NOTE: Note the position of the terminals on the switch and the adapter to insure that the proper connections have been made.

Discard the original ignition switch and ignition keys after kit is installed.

