## SERVICE KIT

753-0600

CODE:

SP-148

DATE:

**APRIL 27, 1994** 

SUBJECT: SERVICE KIT FOR REPLACEMENT

OF CHAIN -- AXLE ASSY., PART NO.

682-7507

## ASSEMBLY INSTRUCTIONS

The original rear flap was assembled to the Chain -- Axle Assy with self tapping screws. The replacement flap, part number 731-1483 is assembled by snapping the rear flap over the axle from the rear.

## 753-0600 CHAIN AXLE ASSY KIT

QTY. PART NO.

**DESCRIPTION** 

682-7513 CHAIN AXLE ASSY

731-1483 REAR FLAP

