

SERVICE KIT

753-0620

CODE: SP-151
DATE: March 14, 1995
SUBJECT: Ground Speed on Model 280 Series (Rear Cog Drive)

Reports from the field have indicated that the ground speed of the model 280 Series (Rear Cog Drive) has been too fast for some people. By installing Service Kit 753-0620, you will slow the unit down by .5 miles an hour.

Kit 753-0620 Consists of:

REF. NO.	PART NO.	DESCRIPTION	QTY.
1	713-0449	9 Tooth Engine Sprocket	1
2	638-0004	Drive Shaft Ass'y.	1
3	16832A	Drive Engagement Cam	1
4	715-0247	Roll Pin	1

